

Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated: 19/06/2025

It is certified that the existing building Sanadi International School, Siddapur
building or premises) at Survey No - 26, Mudhol Road, Siddapur, Tq Jamkhandi
is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground Floor First Floor Second Floor					

The building is owned/occupied by The President Sanadi International School, Siddapur have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Public works Department Jamkhandi on 03/06/2025 (date of inspection) in the presence of The Principal Sanadi International School, Siddapur and that the building/premises is fit for occupancy for running school with effect from 19/06/2025 for a period of Three years in accordance

Issued on 19/06/2025 at Public Works Department, Jamkhandi by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Assistant Executive Engineer
Signature with Seal Public Works Department

Name Sub Division, JAMKHANDI

Designation : _____

Name & Address of Department/ Office: _____


PRINCIPAL
SANADI INTERNATIONAL SCHOOL
SIDDAPUR - 587301, Karnataka
Tq. Jamkhandi, Dist. Bagalkote.
CBSE Affiliation No. 831158 & School Code: 49


EXECUTIVE PRESIDENT
SANADI EDUCATION HEALTH RURAL
DEVELOPMENT TRUST
JAMKHANDI-587301, Dist. Bagalkot

BUILDING FITNESS CERTIFICATE

- 01 Inspecting Officers : Asst Executive Engineer/Assistant Engineer PWD Sub Div
Jamkhandi
- 02 Name of Building : Sanadi International School Siddapur, Taluk Jamkhandi of
Bagalkot District
- 03 Building Permit No : 187/SIS/BFC/2021-22
- 04 Address : Sanadi International School Siddapur, Taluk Jamkhandi of
Bagalkot District
- 05 Description / Classification of Building : Institutional
- 06 Owner : Chairman, Sanadi International School Siddapur
- 07 Period for which the certification is issued : 2025-2028
- 08 Nature of Defects, If any :
a. Foundation & Basement : Good
b. Superstructure : Cracks appeared in walls
c. Doors & Windows : Good
d. Wood Work : Good
e. Roof : Good
f. Flooring : Good
g. Miscellaneous (Crack Etc) : Some Cracks and Dampness appeared in walls & Peeling of
Paint observed which must be Repaired & Existing Lift
maintained on regular basis
- 09 Any Major Defects noticed which will :
render the building unsafe in any manner : None
- 10 Whether maintenance works have been :
done properly : Yes
- 11 Whether the structure is sound or not for :
Occupancy : Yes. Its Safe.

Secretary/Chairman
Chairman, Sanadi International School
Siddapur

Date :-

Consultant
Sarvashri Consultants Pvt Ltd
Jamkhandi

Date :- 03-06-2025

Assistant Engineer
Public Works Dept. Sub Div,
Jamkhandi

Date :- 03-06-2025

CERTIFICATE

This is certified that the building is inspected by me on 03.06.2025 and found to be fit as per the norms of NBC of India 2016 for Occupancy for the period of 2025 -2028 for the reasons stated above.

Assistant Executive Engineer
Public Works Dept. Sub Div, Jamkhandi